

F-2: Jersey Island Photo Log


Photos taken on May 22, 2003



Jersey Island – Looking north along levee road from Station 320+00 (Site 2).



Jersey Island – Looking south from levee road, from Station 320+00 (Site 2).



Jersey Island – inflow from Piper Slough into irrigation ditch, near Station 320+00 (Site 2).



Jersey Island – looking west from levee road near Station 190+00 (high priority area of Site 1).



Jersey Island – landward side of levee, looking east from between Station 180+00 and 190+00 (high priority area of Site 1).



Jersey Island – Near Station 110+00 (end of Site 1, low priority area), looking northwest from levee road at landward side of levee.



Jersey Island – example of active rodent burrows on landward levee slope near Station 120+00.



Jersey Island – looking east along levee near Station 110+00 (end of Site 1).



Jersey Island Borrow Site – view of the northwest portion, from high elevation area east of rubble piles.



Jersey Island Borrow Site – view looking north, from high elevation area east of rubble piles.



Jersey Island Borrow Site – view of the north portion.



Jersey Island Borrow Site – looking west toward rubble piles.